MS4 Annual Report Form

This report is being submitted for the reporting period ending March 9, 2014

If submitting this form as part of a joint report on behalf of a coalition leave SPDES ID blank.

Name of MS4/Coalition: Village of Ballston Spa

SPDES ID: NYR20A376

Minimum Control Measure 3. Illicit Discharge Detection and Elimination

The information in this section is being reported (check one):

- ● On behalf of an individual MS4
- ○ On behalf of a coalition

How many MS4s contributed to this report? ___

1. Enter the number and approx. percent of outfalls mapped: 70 # 100 %

2. How many of these outfalls have been screened for dry weather discharges during this reporting period (outfall reconnaissance inventory)? 67

3.a. What types of generating sites/sewersheds were targeted for inspection during this reporting period?

- ○ Auto Recyclers
- ○ Building Maintenance
- ○ Churches
- ○ Commercial Carwashes
- ○ Commercial Laundry/Dry Cleaners
- ○ Construction Vehicle Washouts
- ○ Cross-Connections
- ○ Distribution Centers
- ○ Food Processing Facilities
- ○ Garbage Truck Washouts
- ○ Hospitals
- ○ Improper RV Waste Disposal
- ○ Industrial Process Water
- ○ Landscaping (Irrigation)
- ○ Marinas
- ○ Metal Plateing Operations
- ○ Outdoor Fluid Storage
- ○ Parking Lot Maintenance
- ○ Printing
- ○ Residential Carwashing
- ○ Restaurants
- ○ Schools and Universities
- ○ Septic Maintenance
- ○ Swimming Pools
- ○ Vehicle Fueling
- ○ Vehicle Maint./Repair Shops
- ○ Other:
- ○ None

○ Sewersheds: